## **ENGINEERING CHANGE NOTICE**

					_	
DART AEROSPACE LTD		Amendment Design Review (ADR) Yes/No. Y				969
Date: 07.06.05			ADR Date: 07.06.0	ECN #:		
Job No: 00056		-	Created By: JC	Checked By:		
Product No: D206-642		Approved By: Approved By:				
Product Name: Skidtube Installations			(Proj. Manager)	(Management if reqd)		
Documents Affected:						
Release D3283 Rev. E						
D3288 Rev. D						
D3289 Rev. C						
# Engineering Actions	Yes	No	Responsible	To happen by:	Comp	olete
1 Required Documents/Drawings Under Review?	X		MB	ASAP	07.05	5.31

#	Engineering Actions	Yes	No	Responsible	To happen by:	Complete
	Required Documents/Drawings Under Review?	Х		MB	ASAP	07.05.31
	Update Blue/Pink Folder/Electronic File		Х			
	Update DSI Folder/Electronic File		Х			
	Update D-Part Master Binder	Х		KJ		07,08,29 KJ
5	Update Grey Project Binder	Х		DC/KJ		07,08,294
6	Update DEO/DSI Binder		Х			
7	Update Master Document List (MDL) &	Х	Х	X		07.08.29 DC
8	Update Document Record (DR) Rev K	Х		KA.DC		07.08.29 BC
9	Update Change Record Form		Х			
10	Move Electronic File	Х		KJ		07.08.29
11	Notify TC of Change		Х			- 0
12	Notify FAA of Change		Х			
13	Update QSI 021 (TC/FAA STC)		Х			
14	Update QSI 036 (K-Kits)		Х			
15	Update Accpac Database		Х			
16	Update Access Database		Х			
17	Verification ARC		Х			
	Update STC Approval List		Х			
19	Update Product Development Summary		X.			
	Create/Update COSS (Estimate/BOM)	Χ		JLM/EC		14/102.09.09
	Create/Update PPP's		Х			
22	Update Paperwork Kits in Production		Χ·			
23	Update Paperwork Kits in Stock		Х			
	Red Tag Stock with old CHG #		Х			
	Rework/Scrap Current Production		X	- <u>-</u>		
26	Rework/Scrap Kits in Stock?		Х			
	Update Qpulse/Laminated Dwgs	X	**	<b>K</b> J		07,08.29 19
	Create/Update Controlled PDF Files	Х				07.08.29 9
	Create/Update FAI sheets	×	*	JL/EC		1907/10.64
	Create/Update CNC Programs	Х		JLM/EC		14/1/07:49.0
	Create/Update Tooling		Х			/ /
	MPP required?		Х			
	Notify Previous Customers		Х			
	Notify Eurocopter France		Х			
35						
36						1

Description / Action:

Update and release D3283 Rev. E, D3288 Rev. D, and D3289 Rev. C Update cutting toolpath for D3283 to ensure manufacturing of 57 holes. Verify D3282 programming and add machining of 57th hole if missing.

Close Engineering portion of NCR#164 and PAR#179

D3288 LAMINATED (LG)

ECN Complete:

Date: 07, Sept 27

	Preventive Action Report						PAR /79		
Raised	by: <sub>(14</sub>	2 11	Source:	70	Ordo Sh	act No	1 of /		
	- Mac	Bellavance	2006	J.C. ins		ieet No. <u> </u>	01_/_		
Issue fo		01/1			Di	,	5/23		
Dept./Su		Mod / LANDIN	GEAK.		D.	<u> </u>			
Product	/Service:	> 20.42	) N 2202			iority.	HIGH LOW		
	04	3283 -	<u> </u>		<u> </u>				
Area of	Standard <i>:</i>	Section A	0110						
QSP		Description of Is:	Sue						
QSPM		D206-64	<i>(</i> 2						
		·							
Desument	~.	Dusis	Specifying 5.	7 holes	but onl	γ			
P/O	<b>5.</b>						ł		
Invoice		Showing 56	. DXF FILE	15 51	how.ng	56 m	ics		
W/O 🌠		PS WELL			)				
	1930/31942	Julian Concil.							
TSR		-							
Drawing									
			Forward	d to Director, Qu	uality Assurance	on completic	on of this box		
DQA: Sectio	n B: Indicate who	is responsible for creating P/							
Section									
Prevent	ive Action	Responsible for Inve	estigation/PA: <u> </u>	5	10 be	done by:			
No   Initial	1	Action Des	scription		Responsible	Due date	Sign/Date		
1. D.T	UPdate	DWS			M.B. DC	01/05/30	07.08.21		
,		· J			12				
J. D.T	Uplate	DOF			JUNIE.C	07/05/30	1 post 6		
3 54.	In work	Sim Ornavess Du	est in second lad	c )	J. Murdel	074523	0705:23,		
3 24.	mphobile	in progress, Du 1. Proceedore wi	h be were ten en 1	the			,		
		the wors	•				·		
				•					
					Fault Ca	tegory:			
Section	С				· · · · · · · · · · · · · · · · · · ·				
Verificat	tion of P/A	Responsible	e for Verification of PA:_				-		
No		Verification Method		Sign	Date				
						rward to DQA on impletion of Verific			
					D	QA:			
						* ***			
					D	ate:			
OA Purpos	son only	,	D/A	Closed	Da	to			

	NCR 164						
Raised by:	Stow. Source: Rich Support.	Sheet No. / of /					
Non-Conforming	, Stow.	Date:					
Dept./Supplier:	Engineering Design.	07/05/16					
Product/Service:	J	Priority: HIGH					
	Dag-642-611/612/63/614.	LOW					
Area of Standard:	Section A Description of Non-Conformance						
QSP Description of Non-Comornance							
- Clamp does not does not fit							
Documents: Detween the Aft saddle and 1							
P/O	Att most groundhandling live	The the					
Documents:  Detween the Aft Saddle and the  P/O Invoice W/O Batch No.  Detween the Aft Saddle and the  Value of the Aft Saddle and the  No dimensions to locate hotes for the  Provided the Saddle and the  Provided the Saddle and the  No.  Death of the Saddle and the  Provided t							
Batch No.	- I wand handling lags on dus	res to the					
TSR	Root cause: Tolerance Stock up						
Drawing	- Previous Since S						
Forward to Director, Quality Assurance on completion of this box							
DQA: Section B: Indicate who Section B	o is responsible for creating C/A, and a completion date. Section C: Indicate w	1 1					
Corrective Action	Responsible for Investigation/CA: W. Bellevance	To be done by: Of 105 130					
No Initial	Action Description Res	sponsible   Due date   Sign/Date					
1. 07 Quaran		J.M. 07/05/17 BURUS17					
·   8		Stor 07.0525 Beg. 05.28					
7 18 Ensure that slamp of the petween CHU P. Stan 070345 18090478							
3. D Fra to revise duy so that a preper Mon B. 107.06.04.07.08. 21.							
4. B. Production, - Eng to applicate doill is 5/11/ 07608 NIA							
de ber due							
5. D.7 Ald to compatibility matrix. ) D.S.							
At ITia is as per Duri and 1 05/9383 WILL							
always as been Rit issue ADDRESS THE							
Fault Category:							
Preventive Action Required: NO YES #							
Section C							
Verification of C/A  Responsible for Verification of CA:  Responsible for Verification of CA:							
No Verification Method Sign Date Forward to DQA on							
Completion of Verification							
		DQA:					
		Date:					
QA Purposes only	N/C Closed	Date					
H:forms\Quality Assurance\ap							

## **Kim Johnston**

From:

David Shepherd [dshepherd@dartaero.com]

ient:

Wednesday, August 29, 2007 10:23 AM

To: Cc: 'Kim Johnston' 'Peter Hum'

Subject:

RE: ECN 969

Kim,

Per this email, please get Peter to stamp them and sign them released. I assume these are original pen signatures and not scanned signatures.

Thanks, David

-----Original Message-----

From: Kim Johnston [mailto:kjohnston@dartaero.com]

Sent: Wednesday, August 29, 2007 6:19 AM

To: David Shepherd (E-mail) Cc: Daniel Campbell (E-mail)

Subject: ECN 969

Hi David,

Dan Campbell gave me ECN 969 releasing drawings D3283, 3288 & 3289 for the D206-642 skidtubes. You initialed them but didn't stamp them released. I've scanned them into the system but let Eric know about the release stamp. we have to do any w/o's using these drawings I was thinking that we can stamp them preliminary until you come here if that's okay with you. Otherwise I can get one of the engineers to sign the release on the drawings per the ECN.

Let me know how to handle this. When are you coming to Dart?

Kim Johnston Dart Aerospace Ltd. Engineering Clerk Document Control

Email: kjohnston@dartaero.com

Tel: 613-632-5200 Fax: 613-632-9311

No virus found in this incoming message.

Checked by AVG Free Edition.

Version: 7.5.484 / Virus Database: 269.12.10/977 - Release Date: 8/28/2007

4:29 PM

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.484 / Virus Database: 269.12.10/977 - Release Date: 8/28/2007

4:29 PM